



Thermography Report



Any Customer
Anytown, NH

Thermography date: (Date)

Weather: (Sunny)



Picture 1. Captured at: Main Entrance




Moisture Content: High

Comment: An elevated moisture is present in the lighter sections of area #1

Recommendation: Recommend removal of the stucco finish and repair as needed. Replace the deteriorated wooden trim above this area and reseal.

Picture 2. Captured at: Left front



Moisture Content: High

Comment: An elevated moisture is present in the lighter sections of area #1

Recommendation: Replace the rotted window and remove the stucco finish and repair as needed.